BOREWELL
COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

Date :.....

No. : 800

1. Customer's Name and Address : AEE. BBMP
   With Telephone No. Byatarayanapura Sub-division
2. Well Location : Jaya Surya layout Agrahara
3. Total Well Depth / Drilled in Ft. : 1208 feet.
4. Casing Erected in Ft. : 197 feet.
5. Water Struck at the Depth of : 670 feet. 900 feet.
6. Total Yield (Measuring method "V" North 2 feet. / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : 1100 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

* Contra * Adc * Mi * G * WO

Scanned by CamScanner

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

Date :.....

No. : 801

1. Customer's Name and Address : AEE. BBMP Byatarayanapura Sub Division
   With Telephone No.
2. Well Location : Srinivasapura.
3. Total Well Depth / Drilled in Ft. : 1214 feet.
4. Casing Erected in Ft. : 214 feet.
5. Water Struck at the Depth of : 810 feet 1020 feet.
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear.
8. At the Depth of : 1020 feet
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned by CamScanner

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 802

Date :.....

1. Customer's Name and Address : AEE. BBMP
   With Telephone No. Byatarayanapura Sub Division
2. Well Location : Dwarkanagara 6th Main
3. Total Well Depth / Drilled in Ft. : 1211 feet.
4. Casing Erected in Ft. : 181 feet.
5. Water Struck at the Depth of : 920 feet.
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear.
8. At the Depth of : 1025 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned by CamScanner

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

Date :.....

No. 803

1. Customer's Name and Address : AEE. BBMP
   With Telephone No. Byatarayanapura Sub Division
2. Well Location : Kathigenahalli Ayyappa Layout Near APP Towers.
3. Total Well Depth / Drilled in Ft. : 1208 feet.
4. Casing Erected in Ft. : 210 feet.
5. Water Struck at the Depth of : 815 feet.
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clay
8. At the Depth of : 1002 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned by CamScanner

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. 804

Date :.....

1. Customer's Name and Address : AEE. BBMP
   With Telephone No. Byatarayanapura Sub Div
2. Well Location : Chamundi Layout 1st Cross
3. Total Well Depth / Drilled in Ft. : 1211 feet. Pathrenahalli
4. Casing Erected in Ft. : 187 feet.
5. Water Struck at the Depth of : 816 feet
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clay.
8. At the Depth of : 1090 feet
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned by CamScanner

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. 805

Date :.....

1. Customer's Name and Address : AEE BBMP
   With Telephone No. Byatarayanapura Sub Division
2. Well Location : Kogilu Layout 6th cross.
3. Total Well Depth / Drilled in Ft. : 1214 feet.
4. Casing Erected in Ft. : 191 feet.
5. Water Struck at the Depth of : 920 feet.
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear.
8. At the Depth of : 1025 feet
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned by CamScanner

VINAYAKA ENTERPRISES

BOREWELL COMPLETION REPORT

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

Date :.....

No. : 806

1. Customer's Name and Address With Telephone No. : AEE. BBMP Byatarayanapura Sub Division
2. Well Location : ~~Kosiku~~ layout Tippunagara
3. Total Well Depth / Drilled in Ft. : 1208 feet.
4. Casing Erected in Ft. : 191 feet.
5. Water Struck at the Depth of : 875 feet.
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition : Boulders / Silt / Loose Soil / Clear : Clear.
8. At the Depth of : 1032 feet.
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. 807

Date :.....

1. Customer's Name and Address : AEE. BBMP
   With Telephone No. Byatarayanapura Sub div
2. Well Location : Babanagara Bhavan Pvt School
3. Total Well Depth / Drilled in Ft. : 1211 feet.
4. Casing Erected in Ft. : 197 feet.
5. Water Struck at the Depth of : 923 feet.
6. Total Yield (Measuring method "V" North 2 inch / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear.
8. At the Depth of : 1102 feet
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned by CamScanner

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

Date :.....

No. : 808

1. Customer's Name and Address : AEE. BBMP
   With Telephone No. Byatarayanapura Sub Division
2. Well Location : MCECHS layout 3rd cross
3. Total Well Depth / Drilled in Ft. : 1214 feet.
4. Casing Erected in Ft. : 204 feet.
5. Water Struck at the Depth of : 965 feet.
6. Total Yield (Measuring method "V" North Failure / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Failure
8. At the Depth of : Failure
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned by CamScanner

BOREWELL
COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

Date :.....

No. 809

1. Customer's Name and Address : AEE. BBMP
   With Telephone No. Byatarayanapura Sub Division
2. Well Location : Krishnadevarayalayout Bagalur
3. Total Well Depth / Drilled in Ft. : 1208 feet.
4. Casing Erected in Ft. : 197 feet.
5. Water Struck at the Depth of : 823 feet,
6. Total Yield (Measuring method "V" North Failure / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Failure
8. At the Depth of : Failure
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / ~~Proprietor~~

Scanned by CamScanner